

**TOP SECRET**

25 YEAR RE-REVIEW

T O P S E C R E T 192216Z

25X1 EMERG

0601

25X1

25X1 REF

A

0593

B

0595

985

**EMERGENCY**

25X1

REF A PARA D. AT 0523Z PILOT OBSERVED BOTH [ ] WARNING  
LIGHTS CAME ON FOR APPROX 20 SEC, AND THEN GO OUT. THIS OCCURRED  
TOTAL OF THREE TIMES OVER APPROX 2 MIN PD. WHILE LIGHTS WERE ON  
PILOT HAD STROBE

ON SCOPE INDICATING POSSIBLE FRUIT SET SITE  
DIRECTLY AHEAD. ALSO HAD HIGH PITCHED AUDIO SIMILAR TO FRUIT SET.  
AT THIS TIME HE MADE LEFT 90 DEG TURN AND LOST INDIC. DURING  
PERIOD 0630-0700Z PILOT HAD INTERMITTENT AND VERY

WEAK SYS 12

INDICATIONS SUCH THAT BARELY READABLE AND UNABLE DETERMINE BEARING.  
POSSIBLY SAME SITE.

T O P S E C R E T

CFN 192216Z 0601 X 0593 0595 1985 A D 0523Z HOURS 128/20 SECN/1 MIN

25X1 STROBE 90 DEG INDIC 0630-0700Z [ ]